

July 22nd, 2021

Dear Doug,

The IEP Audit for the year 2021 is currently underway. It was postponed approximately 90 days due to COVID-19. The *Deviation from the Kalitta Charter's Audit plan Cycle* is attached.

Quality Assurance Audits

The *Quality Assurance Audits* for the first half of 2021 are complete. The Quality Assurance Audit Checklists are attached for your review.

Event Logs

There have been twenty-six Event Logs submitted for the first half of this year. All have been closed. A comparison chart has been included from the entirety of 2020, to the first half of 2021. A record of all event logs to date for 2021 has been attached for your review.

Prepared by:

Matt Price Safety Coord.

Submitted by:

Reviewed by:

Approved by:

Accepted by:

Bruce Anderson

Mgr. of Safety

Ronald Fansler

Dir. Of Airline Safety

Heath Nicholl

Doug Kalitta

Senior V.P./Deputy COO

President/CEO

Memorandum

To: Berry Birurakis General Manager (Accountable Executive) Kalitta Charters

Ronald Fansler Director of Safety Kalitta Charters

From: Bruce Anderson, Auditor

Date: April 21, 2021

Re: Deviation from Kalitta Charters Audit Plan Cycle.

Gentlemen;

If you recall that due to the increased workload on the Safety Department from the COVID-19 pandemic, we postponed the Annual Internal Audit until May 25 2020. Consequently, the 2021 audit will resume its annual schedule and will be commencing on May 3rd 2021. This change in schedule is in accordance with the *Kalitta Charters Internal Audit Program*, page 22 (see attached), the plan cycle may be changed to meet operational requirements necessity but not to exceed 6 months late of the original planned due date.

Respectfully,

Bruce P Anderson Auditor # 1158

Memorandum of Record

Date: June 1 2021

To: Ronald Fansler: Director of Safety Kalitta Charters

From: Bruce Anderson:, Auditor

Subject: Trend Analysis Kalitta Charters Internal Audit Findings / Event logs trends

Good Morning Ron,

Internal Evaluation Audit: In accordance with the Internal Evaluation Program *Trend Analysis* requirements page 17 the auditor is required to report any trends to the Director of Safety. Due to the COVID-19 pandemic the Kalitta Charters Internal Evaluation for 2021 has been postponed, the audit is now scheduled to start June 2021.

Event logs: For the period from January 1-June 1 2021 there was no identifiable trends in the submitted Event logs.


Best Regards,

Bruce Anderson

2021 KC IEP Trending


2


4



2020 KC IEP Trending

S





Question 19-01/101-06 and 20-01/101-06 - Current aircraft list

KALITEN CHARTERS

KALITTA CHARTERS,

QUALITY ASSURANCE MANUAL

Page:

26

Date:

05/10/13

Rev:

		QUALITY ASSURA	NCE AUDIT CHEC	KLISTS	
AUI	DIT TYPE:	ANNUAL		SELF	
AUL	DIT LOCATION:	YIP V		OTHER	
Area Aud	a audited: AIRC litor:	CRAFT MAINTENAN CORAFTA	CE AND INSPECTION Department Repartment Audit Date(s):	ON C. DRATE 1- 28-202	_ ~+ '- 1
appı	ropriate space. A	rmance, "NC" for non-c An Audit Finding Correc . General observations a	ctive Action Form will	be generated for all n	
i.			s being utilized by ma tion being accomplish		rior to
2.		Are current Manufact maintenance function	ures' Maintenance Ma s?	nuals being utilized fo	or all
3,		Are proper tools and efunctions?	equipment being utilize	ed during maintenance)
4.	<u>C</u>	Are computer generat disposed of after use?	ed maintenance manua	l procedures being	
5.		Are inspection person inspect?	nel <u>not</u> involved in per	forming the work that	they
5.	<u> </u>	Is an updated list of al office?	l inspectors kept on dis	splay in the maintenar	nce
7.		Are all maintenance pactivities requiring sec		have access to those	
3,	<u> </u>	Are aircraft inspector current?	raining (including rec	urrent training) record	ls
Zana	ral Observations	and Commanta			

BALITER CHARTERS

KALITTA CHARTERS,

QUALITY ASSURANCE MANUAL

Page:

25

Date:

05/10/13

Rev:

	QUALITY ASSURA	NCE AUDIT CHECKLISTS
AUDIT TYPE;	ANNUAL	SELF .
AUDIT LOCATION:	YIP VIP	OTHER
	LITY ASSURANCE/CO	ONTINUING ANALYSIS & SURVELLANCE Department Rep: Tonolol & Nost
appropriate space. A	n Audit Finding Correct	enformance, or "NA" for not applicable in the tive Action Form will be generated for all non-ind comments will be recorded below.
1. <u>C</u>	Are Quality Assurance	Audits being completed on time?
2. <u>C</u>	Is there and adequate s	staff of trained QA auditors?
3. <u>C</u>	Is a current list of approfice?	oved QA Auditors on display in the Maintenance
4.	Is Root Cause Analysis	s being utilized as required by the QA Manual?
5. <u>C</u>	Are engine and airfram	ne component premature removals being ed per the CAS programs?
6. <u></u>	Are all the evaluation f program being complie	forms, reports and audits required by the CAS ed with and tracked?
7.	Are vendor audits being the CAS program?	g complied with on time and tracked as required by
8. <u>L</u>	Is an Approved Vendor inspectors?	r List maintained and made available to receiving
General Observations	and Comments:	

KALITTA

KALITTA CHARTERS,

QUALITY ASSURANCE MANUAL

Page:

24

Date:

05/10/13

Rev:

		QUALITY ASSURANCE	E AUDIT CHECKL	ISTS
AU	DIT TYPE:	ANNUAL	SI	elf V
AU	DIT LOCATION	YIP V	OTŁ	mer
Au	ea audited: MA	INTENANCE CONTROL	Department Rep: Audit Date(s):	CHUCK DIRATE
Ent app	er "C" for conf ropriate space.	ormance, "NC" for non-conformance, "NC" for non-conformance. An Audit Finding Corrective Acts. General observations and conformations.	Action Form will be a	generated for all non-
1.	<u>C</u>	Is the Daily Status Report	updated daily and be	ing utilized?
2.		Is the Heavy Maintenance	Forecast Report up	dated monthly?
3.		Are the Aircraft Status Bo updated daily?	ards (maintenance o	ffice and flight following)
4.		Are they coordinating aircrawhether scheduled or non-se	ft on the road mainte cheduled, in an as ne	mance requirements eded basis?
5.	<u> </u>	Do they maintain a continuo facilities, arrange for shipping program participation, suppled maintenance personnel and participation of the program of the pr	ng of spares, verify ca y required technical	urrent drug and alcohol data to contract
6.	<u>C</u> _	Do they converse daily with required parts for schedule a	stockroom personne nd non-scheduled ma	for the procurement of hintenance requirements.
7.	<u> </u>	Do they coordinate with the provide accurate aircraft dela	Dispatch and Operati y and status informa	ions department to
Genera	al Observations	and Comments:		

BALITTA CHARTERS

KALITTA CHARTERS,

QUALITY ASSURANCE MANUAL

Page:

23

Date:

05/10/13

Rev:

v: #8

		QUALITY ASSUR	ANCE AUDIT CHECKLISTS
ÀUI	OFT TYPE:	ANNUAL	SELF
AUE	OIT LOCATION:	YIP V	OTHER
Are: Aud	a audited: AIR litor:	CRAFT RECORDS	Department Rep: C. DIZATH Audit Date(s): 1-78-2021
appı	opriate space.	An Audit Finding Corr	conformance, or "NA" for not applicable in the ective Action Form will be generated for all non-and comments will be recorded below.
1.	<u></u>	Aircraft Computer r	uns against actual Airframe Logbook entries.
2.	<u>C</u>	Airframe logbook er	ntries for completeness.
3.	<u> </u>	Computer run times	against actual engine logbook times and/cycles.
4.		Are completed form	s 337 on file and in order?
5.		Are weight and bala	nce records complete and current and on file?
6;	C	Are equipment list re	ecords complete and current and on file?
7. ·	C	Check Inspection pa	ckages for completeness.
8.	. <u>.C</u>	Check Engine logbo	ok and entries for completeness and Accuracy.
9.	<u>C</u>	Check Non-routine f	orms for completeness,
ίο.	\mathcal{L}	Check for Fire block	ing paperwork for completeness and accuracy.
11.	6	Are the condition of	records and files satisfactory?
2.		Check the AD Summ	ary Lists to ascertain that they are completely filed

KALITIA

KALITTA CHARTERS,

QUALITY ASSURANCE MANUAL

Page:

22

Date: Rev: 05/10/13 #8

		QUALITY ASSURA	ANCE AUDIT CHI	ECKLISTS
AUD	IT TYPE;	ANNUAL		SELF V
AUD	IT LOCATION:	YIP V		OTHER
Aud: Ente	itor: la le r "C" for confo opriate space.	ORES / RECEIVING DIDINGLE DIMINGLE DIMINGLE	Audit Date(s): conformance, or "NActive Action Form w	A" for not applicable in the vill be generated for all non- pe recorded below.
1.	<u>C</u>	Repair Agencies used the Approved Vendor		airs or overhauls match
2.	<u>C</u>	Stores Department pe	ersonnel have receiv	ed HazMat shipment training.
3,	<u> </u>	Components are prop number, and serial nu		ntified by name, part
4.	<u>C</u>	BER and Condemned and are stored separat	→	with an attached KC tag, e parts.
5. ⁻	<u>C</u>	Components are store handling damage,	ed to protect them fro	om environmental and
6. ∵			the KC tag and all	elf-Life program reflect components are within
7.	<u>C</u>	Elastrometric material requirements.	ls are procured and	stored per KC
8.	2	Components awaiting area from serviceable		n are stored in a separate

KALITTA CHARTERS,

QUALITY ASSURANCE MANUAL

Page:

21

Date:

05/10/13

				Rev:	<i>77</i> 8
		QUALITY ASSURANCE A	UDIT CHECKL	ISTS	
AUD	IT TYPE:	ANNUAL	SI	ELF	
AUD	IT LOCATION:	YIP V	ОТТ	. ,	
	audited: MAN	AGEMENT & PERSONNEL	Department Rep Audit Date(s):	: Maree 128/202	L Cote
appr	opriate space. A	mance, "NC" for non-conforma An Audit Finding Corrective Act . General observations and comm	nce, or "NA" for i ion Form will be	not applicabl generated fo	le in the
1.	<u>e</u>	Director of Maintenance meet	s the requirement:	s of FAR 11	9.71e.
2.	<u>e</u>	Duties, responsibilities, and au Maintenance are detailed in th FAR 135.23.			i by
3.		Certificate status of all Airfran repairmen employed is confirm	-		
4.	C	Sufficient qualified technician maintain the company's aircra			
5;	C	Written procedures exist for spengine run-up, and aircraft tax		ns (inspectio	n,

KALITUA CHARTERES

KALITTA CHARTERS,

QUALITY ASSURANCE MANUAL

Page:

20

Date:

05/10/13

Rev:

#8

		QUALITY ASSURANC	E AUDIT CHECKLISTS
AUD	IT TYPE:	ANNUAL	SELF
AUDI	IT LOCATION:	YIP V	OTHER
		NTENANCE TRAINING	Department Rep: Jim Keffer Audit Date(8): / - Z 7 - Z 1
appro	opriate space. 🛭 🕹	An Audit Finding Corrective	ormance, or "NA" for not applicable in the Action Form will be generated for all non-comments will be recorded below.
1.	<u> </u>	The current training status	s of each technician is identified.
2.	_0_	Training files contain reco	ords on KC and contract technicians (if
3.	C	Required formal / recurrer documented in accordance	nt training is accomplished and with KC requirements.
4.	<u> </u>	OJT is documented for each	ch technician.
5,		Maintenance Personnel ha	we received MEL training and that training
5,			Run-Up and Taxi authorizations meet t training requirements and the is documented.

KALITTA CHARTERS,

Page:

	Ųυ	ALIIY ASSURANC	E MANUAL	Date: Rev:	05/10/: #8
		QUALITY ASSURANCI	E AUDIT CHECKLI	STS	,
AUI	OIT TYPE:	ANNUAL	SE	CLF V	
AUD	DIT LOCATION:	упр 🔽	отн		
	a audited: MAI litor: <i>Mancel</i>	NTENANCE MANUALS - Cofe	Department Rep: Audit Date(s):	Maneal 128/202	Cota 1
appr	opriate space. A	mance, "NC" for non-confor An Audit Finding Corrective . . General observations and co	mance, or "NA" for n Action Form will be g	ot applicable generated for	in the
1.	<u>a</u>	The Director of Maintenan Company manuals used to by Kalitta Charters.			
2.	C	The subscription status of t by the Director of Mainten	~	is maintaine	d
3.	L	The Director of Maintenant Company manual(s) for the Company manuals.			
4.	<u>e</u>	Shop computers are kept el	ean and operational,		•
5.	<u>c</u>	Revised manuals kept by thas "Master" and separated i			eled

KALITEN CHARIBRS

KALITTA CHARTERS,

QUALITY ASSURANCE MANUAL

Page:

15

Date:

06/29/15

Rev:

#10

•	QUALITY ASSUR	ANCE AUDIT CHEC	CKLISTS		
AUDIT TYPE:	ANNUAL		SELF		
AUDIT LOCATION:	YIP		OTHER		
Area audited: FUEL Auditor: Helbert Audit Date(s): /-27-2/ Enter "C" for conformance, "NC" for non-conformance, or "NA" for not applicable in the					
appropriate space. A	An Audit Finding Corre . General observations	ctive Action Form wil	l be generated for all non-		
1. <u>C</u>		weekly, monthly and a sing accomplished and	annual fueling vehicles are up to date.		
2		chicles for fuel contam ds are preformed as re			
3. <u>C</u>		les and equipment ins ance with Kalitta Char	•		
4.		cles and storage area i free from fire hazards.	s maintained in a neat		
5. <u>C</u>	Written procedures en	kist for guidance of fli	ght crews when		
6. <u>C</u>	fuel contamination, p	re available to the fligh rotection from fire haz sengers when refueling			

KALITON CHARTERS

KALITTA CHARTERS,

QUALITY ASSURANCE MANUAL

Page:

16

Date:

05/10/13

	ZOLIZZ Z ZZWO OZRIZI (OZ INIZI (OZ INIZI)	Rev:	#8
,,	QUALITY ASSURANCE AUDIT CHECK	LISTS	
AUD	IT TYPE: ANNUAL	SELF	ura
AUDI	IT LOCATION: YIP V	THER	
	audited: MAIN BASE AUDIT itor: Audit Date(s): /-	'im Keff 27-21	ler
appro	r "C" for conformance, "NC" for non-conformance, or "NA" for opriate space. An Audit Finding Corrective Action Form will be ormance entries. General observations and comments will be rec	generated for	in the all non-
<u>Main</u>	n Base Audit		
1. 4	Audit Technical Manuals with emphasis on the following:		
<u>e</u>	General condition of workstation computers.		-
<u> </u>	All uncontrolled manuals and training manuals are marked "FO and separated from revised manuals.	R REFERENC	E ONLY"
<u>C</u>	All revised paper manuals are in good and legible condition.		
2. A	Audit tool/test equipment program with emphasis on the follow	ving:	
0	Adequate process in place to ensure proper calibration and track	ing of precisior	a tools,
<u>c</u>	Calibrated tools/gages are within due dates.		
C	Tools and test equipment properly stored.		
<u>C</u>	Adequate tools and test equipment available for use for the type work performed.	of aircraft hand	dled and
<u>C</u>	Check servicing units for proper markings and capping of hose	ends.	
. A	udit material and component storage areas with emphasis on	the following:	
0	Consumable parts/materials in work areas - Shelf life limits obse	erved per to KC	C Limits.
C	No unlabeled containers.		

RALITTA CHARTERS

Main Base Audit (cont.)

Check tow bars for condition.

KALITTA CHARTERS,

QUALITY ASSURANCE MANUAL

Page:

17

Date:

09/14/09

Rev:

4	A THE RESIDENCE AND A STREET AND A STREET AS A STREET	,

3.	Audit material and component storage areas with emphasis on the following: (cont.)
<u></u>	Proper identification of removed-serviceable, repairable, and serviceable components.
<u>C</u>	Adequate protection of parts against the elements.
<u>c</u>	Proper storage of flammable materials in a fireproof cabinet.
<u>C</u>	Oil / hydraulic fluids, and servicing equipment, are secured and not left open to contamination.
4. .	Audit Hangar personnel with emphasis on the following:
<u></u>	Familiarity in the use of aircraft log book.
	Familiarity in KC MEL procedures.
C	Proper method of recording discrepancies and corrective action per KC procedures.
0	Proper use of work forms and inspection cards.
5 .)	Ramp area:
<u>C</u>	Cleanliness and absence of foreign objects.
0	General condition of aircraft, if available.
б. С	Ground equipment:
0	Safe and proper operation.
C	Tire condition.
0	Operation of parking brakes.
C	Availability of fire extinguishers.

KALITTA CHARTERS

KALITTA CHARTERS,

QUALITY ASSURANCE MANUAL

Page:

18

Date:

09/30/13

Rev: #

7.	Safety and fire precaution with emphases on the following:	
<u> </u>	Condition of ladders and work stands.	
C	Condition of aircraft jacks.	
<u>C</u>	Condition of hydraulic mule.	,
<u>C</u>	Fluid dispensing containers are properly labeled.	
C	Availability and serviceability of fire extinguishers.	
<u></u> <u> </u>	Check Battery operation of Emergency Exit/Lighting.	
<u>_e</u>	Check expiration date of eye wash solutions.	
<u>C</u>	Observance of no smoking rules.	
<u>C</u>	Check Hangar area for hazardous areas, oil spills and overall neatness.	

No unlabeled containers.

KALITTA CHARTERS,

Page:

16

	QU	ALILI ASSUL	ANCE MANUA	L Date: Rev:	05/10/13 #8
		QUALITY ASSU	RANCE AUDIT CHEC	KLISTS	
AUDI	T TYPE:	ANNUAL		SELF	
AUDI	LOCATION:	YIP		OTHER DO	<i>J.</i>
Area a		N BASE AUDIT	Department Rep: KAudit Date(s): 5	emeth An 1312021	n strong
approp	priate space. 🛭 A	An Audit Finding Cor.	r-conformance, or "NA" rective Action Form will s and comments will be	be generated for	e in the all non-
<u>Main</u>	Base Audit				
1. A	udit Technica	l Manuals with empl	asis on the following:		
<u></u>	General condi	ition of workstation co	omputers.		
<u>C</u>	All uncontroll and separated	led manuals and traini from revised manuals	ng manuals are marked "	FOR REFEREN	CE ONLY"
<u>C</u>	All revised pa	per manuals are in go	od and legible condition.		
2. At	udit tool/test e	quipment program v	vith emphasis on the fol	lowing:	
<u>C</u>	Adequate proc	ess in place to ensure	proper calibration and tra	cking of precisio	n tools.
2	Calibrated too	ls/gages are within du	e dates.		
6	Tools and test	equipment properly st	cored.		
<u>C</u>	Adequate tools work performe	s and test equipment a ed.	vailable for use for the ty	pe of aircraft han	idled and
Com	Check servicin	ig units for proper mai	kings and capping of hos	se ends.	
3. Au	ıdit material aı	nd component storag	ge areas with emphasis o	on the following	·
<u> </u>	Consumable pa	arts/materials in work	areas - Shelf life limits o	bserved per to Ke	C Limits.

Main Base Audit (cont.)

KALITTA CHARTERS,

QUALITY ASSURANCE MANUAL

Page:

17

Date:

09/14/09

Rev:

#5

3.	Audit material and component storage areas with emphasis on the following: (cont.)
<u>C</u>	Proper identification of removed-serviceable, repairable, and serviceable components.
ENA.	Adequate protection of parts against the elements.
NIA	Proper storage of flammable materials in a fireproof cabinet.

Oil / hydraulic fluids, and servicing equipment, are secured and not left open to contamination.

Audit Hangar personnel with emphasis on the following: Familiarity in the use of aircraft log book. Familiarity in KC MEL procedures. C Proper method of recording discrepancies and corrective action per KC procedures. Proper use of work forms and inspection cards.

Ramp area:

- Cleanliness and absence of foreign objects.
- General condition of aircraft, if available.

Ground equipment:

- \mathcal{L} Safe and proper operation. C Tire condition. C Operation of parking brakes.
- Availability of fire extinguishers.
- <u>C</u> Check tow bars for condition.

KALITEA

KALITTA CHARTERS,

QUALITY ASSURANCE MANUAL

Page:

18

Date:

Rev:

09/30/13

#9

/+ N	safety and the precadion with emphases on the following:
	Condition of ladders and work stands.
	Condition of aircraft jacks.
NA	Condition of hydraulic mule.
<u>(</u>	Fluid dispensing containers are properly labeled.
<u>C</u>	Availability and serviceability of fire extinguishers.
<u>NIA</u> -	Check Battery operation of Emergency Exit/Lighting.
<u>v(</u> 1	Check expiration date of eye wash solutions.
<u>C</u>	Observance of no smoking rules.
MA	Check Hangar area for hazardous areas, oil spills and overall neatness.

Page 1 of 7

2021 Safety Event Record

Event Type: Acft Config.: Routing: Event Closed:	3/18/21		3/18/2021	4/8/2021
Routing	N R/N		Z Z	N. N.
Acft Config.:	On approach		During ground operations	On approach
	Air Turnback		Fuel Dump	Emergency Declared
Date/Time Event:	1/20/21 / 2230z		2/8/21 / 2230z	2/11/21 / 0603z
Corrective Action:	Mainteance repaired the aircraft		Crewmember was counsled	Mainteance repaired the landing gear switch.
Event Description:	N820CK Aircraft would not pressurize on departure.		While refueling the aircraft, the XFER switch was in the wrong postion, this resulted in a small fuel spill.	On approach into Burbank Airport the left gear did not indicate down and locked. The crew went into a hold and worked the checklsits, but could not get a safe indication. The crew delcared an emergecy and made a safe landing at KLAX
A/C No:	N820CK	21-01	N73CK 21-02	N73CK 21-03

N451CK 21-04	Enroute to KMLB the weather deteriorated faster than forecasted. We did not have the visibility to accept the approach into KMLB we then diverted to KMCO which had weather above landing minimums and landed without incident. the cargo was then picked up by currier and delivered to the client.	No Corrective Action.	2710/21 /0630z	Diversion due to weather.	Enroute	KMBL	4/21/2021
N451CK 21-05	Aircraft pressurization problem after take-off, aircraft returned to KAUS.	Purged the Pitot Static System	2/12/2021 / 2/ 0010z	Air Tumback	Enroute	30NM W of AUS	5/7/2021
N913CK 21-06	Window heat issue lead to aircraft windows fogging up after landing, aircraft right main and nose gear went off taxiway, no damage noted.	R+R tires and brakes on number 3 and 4	2/13/21 /0730z	Taxi Event	Taxinng	N/R	5/7/2021
N451CK 21-07	N451CK Origanal destination fogged in, flight diverted to KMCO.	None	2/12/21 / 0620z	Diversion due to Weather	On approach	N/R	4/21/2021

Corrective Action:

Event Description:

Event Closed:	5/7/2021	5/27/2021	5/7/2021	5/27/2021
Routing:	Z R	Z/S	Z Z	N/N
Event Type: Acft Config.: Routing: Event Closed:	enroute	On approach	enroute	Taxing
	Decompression	Deviation from assigned altitude	Air Tumback	Taxi Event
Date/Time Event:	2/11/2021 / 2350z	2/14/2021 / 01052	2/16/2021	2/18/2021 / 0930z
Corrective Action:	Maintence Purged Pitot / Static System	Chief Pilot counsled crew,	System ops checked good, no further issue	Aircraft inspected and returned to service after both main gear wheels and brakes replaced
: Event Description:	On climb out from HOU, we started getting fault warnings. At FL400 we noticed that we were losing pressure, the cabin was climbing rapidly. We responded by doing an emergency decent. Once we were at 10,000 feet, we decided to divert to AUS. Landed with no issues.	While flying the ZOMBZ Three STAR to the ILS35R we crossed XPATH at 11,000 but did not decend to cross XBEE at 9,000 as depicted on the approach chart. We were informed of our mistake by the approach controller and corrected our flight path.	After takeoff in climbout lost cabin pressure at 15,000. Returned to KBUR.	After entering the FBO ramp area from Taxiway S the left main gear exited the paved surface. Was able to return the left main gear to the paved surface.
A/C No:	N451CK 21-08	N905CK 21-09	N73CK 21-10	N905CK

Event Type: Acft Config.: Routing: Event Closed:	N/R 5/27/2021	40U-0KC-HOL 7/9/2021	N/R 5/13/2021	N/R 5/14/2021
Acft Config.:	Take-off	Taxing	In-flight	On take-off
	Rejected Takeoff	Aircraft taxied of taxiway	Air Tumback	Air Tumback
Date/Time Event:	2/20/2021 / 1615z	2/28/21 / 0625z	3/15/21 / 0200z	3/17/21 / 1625z
Corrective Action:	None	The aricraft was towed to the ramp, and inspected for damage, noe found.	None, system reset in flight.	Mainteacne repaired the A/C
Event Description:	RTO due to emergency Cabin system valve opened when take-off power was set.	While taixing in low visibilty conditions the crew taxied off the taxiway and ended up in the mud.	Climbing through 8000 feet the emergency bleed activated and would not reset, the fligh returned to OKC	Air turn back on a Air Amburlance trip, following a right fuel computor light. (See event log for full
A/C No:	N870CK 21-12	N71CK 21-13	N71CK	N870CK

7/14/2021	7/14/2021	7/14/2021	7/12/2021
NA	N	N/R	N/N R
On take-off	Take-off	On-ramp	En-route
Air Turnback	ATC issues (Tower)	Minor aircraft damage	Weather diverson
4/3/21 /0130z	4/24/2021 /01202	4/21/2021 / 1830L	4/24/2021
MX adjusted the nose gear up switch, no furhter reports of issues.	Crew counseled on proper ATC procedures.	Crewmember counseled on standard procedures	None
After gear retraction the nose gear unsafe light came on, recycled gear returned to KYIP.	Aircraft took off with out proper clearance, see event log for additional details.	After start aicraft started rolling causing damage to the ground power plug.	Enroue to KDHN weather deterioted, diverted to KECP.
N357CK 21-16	N357CK 21-17	N35WL 21-18	N295CK 21-19

Corrective Action:

Event Description:

N357CK Flight planned to land at KCCR diverted to KCEC due to weather. 21-20	None	6/4/21 / 0100z	Diversion due to Weather	Enroute	N/R	7/12/2021
N905CK Minor fuel spill during fueling due to failed jettison valve. 21-21	Spill cleaned up, refueling procedures revied.	5/30/2021 / 2300Z	Fuel or Hazmat Spill or Incident	On the ramp	N/A	7/12/2021
N870CK 35 mins out of KYIP, the primary inverter failed the aircraft returned to KYIP.	Mainteance Removed and Replaced the inverter, no furhter reports of any issues.	6/16/2021 / 1330z	Air Tumback - Other	Enroute	YIP-BHM	7/12/2021
N229CK During prefight a crew member burned hand on the pitot tube. 21-23	None	7/1/2021 / 1115z	Minor injury to crewmember	Оп Катр	N/R	7/12/2021

Corrective Action:

Event Description:

7/12/2021	7/12/2021	7/22/2021
KYIP-KMSY	Z Z	Z Z
Enroute	enroute	Enroute
Communication Loss or Failure	Electrical issues	Diversion
6/30/2021 / 1415z	7/1/2021 / 04002	7/17/21 / 1500z
none at this time, to date no regulatory inquerys	Mainteance inspected the aircraft, no operational issue found, aircraft returned to service.	Maintenance replaced the inverter.
Enroute the flight the crew lost communication with ATC, after a short time they found the correct freq and were able to reestablish com.	N808CK In flight aircraft had several electrical issues, crew declared emergency and landed at KBNA. 21-25	N913CK Diversion due to weather, enroute to the diversion airport the primary inverter failed, the 21-26 company had the flight divert to KYIP for repairs
N229CK 21-24	N808CK 21-25	N913CK 21-26

Corrective Action:

Event Description:

